

Practitioner's Docket No. F-8505



colc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number : US 6,786,172 B1
Patentee : Leonard Loffler
Issued : Sep. 7, 2004
Art Unit : 3617
Examiner : Lars A. Olson
Title : Shock Absorbing Boat
Docket No. : F-8505
Customer No. : 24131

Certificate
OCT 12 2004
of Correction

Commissioner for Patents
P.O. Box 1450,
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.
2. The Document where the errors are shown correctly in the application file are:


Figures 3 and 4 appear correctly on the Final Amendment filed on July 22, 2004 in the U.S. Patent and Trademark Office.

3. Please send the Certificate to:

Name : LERNER AND GREENBERG, P.A.
Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

☐ Assignment recorded on

Reel : _____
Frame: _____


WERNER H. STEINER (Name of authorized person signing)
REG. NO. 34,956

Attorney of Record
Title of authorized person signing

☐ Attached is a Recordal of assignment

☐ Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)"
(establishing the right of the assignee to take action in this case)

Date: Sept. 30, 2004

OCT 12 2004


Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,786,172 B1
ISSUED : Sep. 7, 2004
INVENTOR(S) : Leonard Loffler

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Figure 3 should appear as follows:



MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,786,172

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 12 2004


Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,786,172 B1
ISSUED : Sep. 7, 2004
INVENTOR(S) : Leonard Loffler

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Figure 3 should appear as follows:



MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,786,172

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 12 2004

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)


UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,786,172 B1
ISSUED : Sep. 7, 2004
INVENTOR(S) : Leonard Loffler

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Figure 4 should appear as follows:

Fig.4



MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,786,172

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 12 2004


UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : US 6,786,172 B1
ISSUED : Sep. 7, 2004
INVENTOR(S) : Leonard Loffler

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Figure 4 should appear as follows:

Fig. 4



MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,786,172

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

OCT 12 2004